

Work completed between 09/01/2020 and 09/30/2020 included the following:


- Continued construction and perimeter air monitoring.
- Continued turbidity monitoring during in-river work.
- Continued transportation and disposal of impacted material to the project landfill.
- Continued site restoration activities (see Photo No. 1 and No. 2).
- Began demobilization activities.
- Performed inspections of the installed sedimentation controls, in accordance with the Soil Erosion and Sedimentation Control permits.

Upcoming work includes the following:

- Complete restoration activities.
- Complete turbidity monitoring during in-river work.
- Complete construction and perimeter air monitoring.
- Complete demobilization activities.
- Continue inspections of the installed sedimentation controls.

Associated pictures:

Photo No. 1: Restoration Activities – Installation of Bank Armoring Stone (photo taken facing north)



Associated pictures:

Photo No. 2: Restoration Activities – Installation of Orange Demarcation Fabric and Sand (photo taken facing northeast)

