

MONTHLY PROGRESS UPDATE #21 MANISTEE, MI FORMER MGP SITE



Work completed between 08/01/2020 and 08/31/2020 included the following:

- Completed in-river sediment dredging (see Photo No. 1).
- Continued construction and perimeter air monitoring.
- Continued turbidity monitoring during in-river work.
- Completed post-removal confirmation observations.
- Completed transportation and disposal of dewatered sediment to the project landfill (see Photo No. 2).
- Began restoration activities at the Operational Site (see Photo No. 3).
- Performed inspections of the installed sedimentation controls, in accordance with the Soil Erosion and Sedimentation Control permits.

Upcoming work includes the following:

- Continue restoration activities.
- Continue inspections of the installed sedimentation controls.
- Continue turbidity monitoring during in-river work.
- Continue construction and perimeter air monitoring.
- Begin demobilization activities.

Associated pictures:

Photo No. 1:
Sediment dredging
(photo taken facing west)



Associated pictures:

Photo No. 2:

Loading a truck with dewatered sediment for transportation and disposal offsite
(photo taken facing north)



Associated pictures:

Photo No. 3:
Restoration activities
(photo taken facing northwest)

