

## **MONTHLY PROGRESS UPDATE #20 MANISTEE, MI FORMER MGP SITE**



### **Work completed between 07/01/2020 and 07/31/2020 included the following:**

- Continued in-river sediment dredging (see Photo No. 1 and Photo No. 2).
- Continued construction and perimeter air monitoring.
- Continued turbidity monitoring during in-river work.
- Continued post-removal confirmation observations.
- Continued transportation and disposal of dewatered sediment to the project landfill (see Photo No 3.).
- Performed inspections of the installed sedimentation controls, in accordance with the Soil Erosion and Sedimentation Control permits.

### **Upcoming work includes the following:**

- Complete in-river sediment dredging.
- Complete post-removal confirmation observations.
- Complete transportation and disposal of dewatered sediment to the project landfill.
- Begin restoration activities.
- Continue inspections of the installed sedimentation controls.
- Continue turbidity monitoring during in-river work.
- Continue construction and perimeter air monitoring.

**Associated pictures:**

Photo No. 1:  
Sediment dredging  
(photo taken facing east)



**Associated pictures:**

Photo No. 2:  
Sediment dredging  
(photo taken facing west)





**Associated pictures:**

Photo No. 3:  
Transporting dredged sediment for dewatering  
(photo taken facing northwest)

