

MONTHLY PROGRESS UPDATE #15 MANISTEE, MI FORMER MGP SITE



Work completed between 12/01/2019 and 12/31/2019 included the following:

- Performed inspections of the installed sedimentation controls, in accordance with the Soil Erosion and Sedimentation Control permit.
- Conducted construction and perimeter air monitoring.
- Transported and disposed of debris offsite to the landfill.
- Completed ISS drilling at the operational site (see Photo No. 1).
- Completed removal of in-water ISS swell material to the restoration elevations inside the coffer dam (see Photo No. 2).
- Began removal of the resuspension control system.
- Performed turbidity monitoring during in-river work.
- Began demobilization of equipment, material and personnel.

Upcoming work includes the following:

- Continue inspections of the installed sedimentation controls.
- Continue construction and perimeter air monitoring.
- Continue turbidity monitoring during in-river work.
- Complete transportation and disposal of debris offsite to the landfill.
- Complete removal of the resuspension control system.
- Complete demobilization of equipment, material and personnel for the current scope of work. Remediation efforts are expected to resume in the spring of 2020.

Associated pictures:

Photo No. 1:
Operational Site- ISS drilling.
(photo taken facing northeast)



Associated pictures:

Photo No. 2:
Operational Site- ISS swell removal.
(photo taken facing west)

