

## **MONTHLY PROGRESS UPDATE #13 MANISTEE, MI FORMER MGP SITE**



### **Work completed between 10/01/2019 and 10/31/2019 included the following:**

- Performed inspections of the installed sedimentation controls, in accordance with the Soil Erosion and Sedimentation Control permits.
- Conducted construction and perimeter air monitoring.
- Transported and disposed of debris offsite to the landfill.
- Continued construction of support platforms to allow ISS drilling inside the cofferdam at the operational site (see Photo No. 1).
- Continued ISS drilling at the operational site (see Photo No. 2).
- Performed turbidity monitoring during in-river work.

### **Upcoming work includes the following:**

- Continue inspections of the installed sedimentation controls.
- Continue construction and perimeter air monitoring.
- Continue ISS drilling at the operational site.
- Continue support platform construction.
- Continue turbidity monitoring during in-river work.

## Associated pictures:

Photo No. 1:  
Operational Site- Support platform construction.  
(photo taken facing northeast)



## Associated pictures:

Photo No. 2:  
Operational Site ISS drilling.  
(photo taken facing west)

