

Work completed between 05/01/2019 and 05/31/2019 included the following:

- Continued mobilizing personnel, equipment and supplies for 2019 construction activities.
- Continued excavation of the former relief holder (FRH) ISS area (see Photos 1 and 2). Transporting and stockpiling overburden soils to the staging area.
- Began In-Situ Solidification/Stabilization (ISS) mixing at the FRH work area (see Photo 3).
- Performed inspections of the installed sedimentation controls, in accordance with the Soil Erosion and Sedimentation Control permits.
- Conducted construction and perimeter air monitoring.
- Transported and disposed of debris offsite to the project landfill.

<u>Upcoming work includes the following:</u>

- Continue mobilizing personnel, equipment and supplies for 2019 construction activities.
- Complete excavation of the FRH ISS overburden material.
- Continue ISS mixing at the FRH work area.
- Begin FRH restoration activities.
- Continue inspections of the installed sedimentation controls.
- Continue construction and perimeter air monitoring.

Associated pictures:



Associated pictures:



Associated pictures:

